RG104 E-1 Box 136 Oct-Dec 1885

Moint of the United States
Thelador Cch 26 hps-Hon. Daniel Mo. For Esq. In regards to the Condition of the Water closets of the U. S. mint at Philada I would State that we have the ordinary Common Hooppers in the basement fourling and four short mangers as there is no way of bentitating them the odor from them Sometimes is very offensive and Consequently unhealthy. I reccommended some time ago that these be taken out and the Danitary Thush Closets put in this change abould be made as som as possible There are also four Demerest Water Clisels on the second floor two being in the adjusting room where the ladies are employed. They are ventilated and in use

about every 3 minuels. I also suggest that flush Closets be put in, there on account of there not being enough watersupply to be used as often as necessary. This Drould Come from a private tank over the desets of the other two Demerest Closets one is should the use of the Superintendents an another for the assayer. Weither is Ventilated and the oder from both is very offensine on damp days All of these should be taken out and the main pipes be bentitated and the flush closets substituted and each provided with private reservoirs to be flushed every time they are used Iwould also Rug gest that a small room be set apart as a wash room and all the closets that are in the basement be put in one room and with the necessary openings for the employees for washing Themselves

Danie a Reins Plumber

Report om Water Closets in the Muit at Philadelphia

Story	No. Kind, and name of manifactura	Long or Short hoppe	Consistion
Basement	8 Wahen Closeks	4 long 4 short	very bad
1"Story			
and Story	4 Demerest Bloschs	12.	middling
3w Story			
4 Story			4
Remarks	Lee accompanying commu	niation	

1885

Quetodian

1082/2 RG104 E-1 Box 136 Oct-Dec 1885 Phila . Pa. Oct 26/83 Same & Heins Relating to louter Close's of Reca Oct 26/83[Abstract:] Relating to water closets of Mint.

Mint of the United States Philada. October 26, 1885

Hon. Daniel M. Fox Esq. Supt. U.S. Mint

Sir

In regards to the condition of the water closets of the U.S. Mint at Philada. I would state that we have the ordinary common stoppers in the basement four long and four short and as there is no way of ventilating them the odor from them sometimes is very offensive and consequently unhealthy. I recommended some time ago that these be taken out and the Sanitary Flush Closets put in this change should be made as soon as possible. There are also four Demerest Water Closets on the second floor two being in the Adjusting Room where the ladies are employed. They are ventilated and in use about every 3 minutes. I also suggest that flush closets be put in, these on account of there not being enough water supply to be used as often as necessary. This should come from a private tank over the closets of the other two Demerest Closets one is for the use of the Superintendent an another for the Assayer. Neither is ventilated and the odor from both is very offensive on damp days. All of these should be taken out and the main pipes be ventilated and the flush closets substituted and each provided with private reservoirs to be flushed every time they are used I would also suggest that a small room be set apart as a wash room and all the closets that are in the basement be put in one room and with the necessary openings for the employees for washing themselves.

Very respectfully yours Saml. A. Heins, Plumber

NARA RG104, Entry 1, Box 136

[Enclosed chart:]

Report on Water Closets in the Mint at Philadelphia.

Story	No.	Kind, and name of	Long or short	Condition
		manufacturer	hopper	
Basement		8 water closets	4 long 4 short	Very bad
1st Story				
2nd Story		4 Demerest Closets		middling
3rd Story				
4th Story				
Remarks		See accompanying		
		communication		

1885 Custodian